

Hawkeye Aircraft Acquisitions LLC  
P.O. Box 345  
Safety Harbor, Florida 34695  
727.796.0903



**2011 Hawker Beechcraft Hawker 900XP Serial # HA-178**

Aircraft				Performance			
<b>Mfg:</b>	Hawker	<b>Model Year:</b>	2011	<b>Ramp Wt:</b>	28,120 lbs	<b>Rcmd Cruise:</b>	430 kts
<b>Model:</b>	900XP	<b>Registration:</b>	N76CS	<b>MTOW:</b>	28,000 lbs	<b>Max Cruise:</b>	448 kts
<b>Serial:</b>	HA-178	<b>Total Time:</b>	3,272	<b>Max Landing Wt</b>	23,350 lbs	<b>NBAA Range:</b>	2,825 NM
<b>C of A:</b>	Feb-11	<b>Landings:</b>	2,433	<b>MZFW:</b>	18,450 lbs	<b>Svc. Ceiling:</b>	41,000 ft

Maintenance and Service Plans		Engine / APU	
Engines on MSP -2018 rate is \$293.08 per hour		<b>Engine Model:</b>	Honeywell TFE731-50R
APU on MSP -2018 rate is \$78.72 per hour		<b>LH SN#:</b>	P122405
Avionics on CASP		<b>LH TSN:</b>	3,174
Times and cycles as of 12/18/2018		<b>LH CSN:</b>	2,349
No known damage history		<b>RH SN#:</b>	P122406
One Fortune 500 US Owner		<b>RH TSN:</b>	3,272
CAMP Maintenance Tracking		<b>RH CSN:</b>	2,433
		<b>APU Model:</b>	Honeywell GTCP-36-150W
		<b>APU SN#:</b>	P1201
		<b>TSN:</b>	1,661

Avionics		Inspections	
<b>Collins Pro Line 21</b>		"B" Check Due:	3,835
<b>Comm:</b>	Dual VHF-4000 digital CNS Radios	"C" Check Due:	4,635
<b>Nav:</b>	#1 NAV-4000/#2 NAV-4500	"D" Check Due:	6,235
<b>FMS:</b>	<b>Dual FMS-6000's with WAAS/LPV</b>	"E" Check Due:	Jan-19
<b>Autopilot:</b>	FGC-3000	"F" Check Due:	Jan-19
<b>Flight Director:</b>	Dual FGC-3000	"G" Check Due:	Jan-19
<b>Radar:</b>	TWR-850 Turbulence Detection Radar		
<b>ADF:</b>	NAV-4000	<b>Additional Equipment</b>	
<b>DME:</b>	Dual DME-4000's	Collins Airshow 21 Cabin Mangement System	
<b>RMI:</b>	Displayed in PFD's	Airshow 4000 w/Flite Deck Controller	
<b>Audio Panel:</b>	Dual db Systems Model 700's	Cabin Audio/Video Entertainment System	
<b>Transponders:</b>	<b>Dual TDR-94D with ADS-B Textron SB 34-4148</b>	Auxiliary A/V Package	
<b>Radio Altimeter:</b>	ALT-4000	Computer Display Capable on Either Monitor	
<b>TCAS:</b>	TCAS-4000	110 VAC/Outlets in cabin and Cockpit	
<b>CVR:</b>	Universal CVR-120	Dual 15" Monitors	
<b>HF:</b>	Collins HF-9000 with SELCAL	4 Channel XM Radio	
<b>Additional Equipment</b>		Custom Galley	
<b>Phone:</b>	Aircell ST 3100, 2cordless handsets and Aircell Axxess II System	Coffee Maker	
<b>Internet</b>	<b>ATG 4000 Aircell High Speed Internet</b>	Microwave	
	<b>Dual FSU-5010 File Server Units (Paperless Cockpit)</b>	<b>Interior</b>	
	ACSS TAWS+ Ground Proximity Warning System	Bubinga High Gloss Wood	
	ARTEX C406-N ELT	Corian Tumbleweed Counter Top	
	Satellite ACARS Interface	Sand Ultra Synthetic Headliner and Window Panels	
	Collins ACARS Datalink w/XM (US Weather only.)	Beige Fabric Lower Side Panel	
	Pulselite System with TCAS Interface	Carpet Tiffin	
	Long Range Oxygen	Bronze Medium Aged Plating	
	Dual Panel Cockpit Doors		
	Belted Lavatory Seat		
	Drop Down Arm Rests		

Interior	
Bubinga High Gloss Wood	
Corian Tumbleweed Counter Top	
Sand Ultra Synthetic Headliner and Window Panels	
Beige Fabric Lower Side Panel	
Carpet Tiffin	
Bronze Medium Aged Plating	

Exterior	
New Paint Nov 2017 by Constant Aviation	
White with Blue and Yellow stripes	

Last Revision Date:12/18/2018

<b>For More Information Contact:</b>	<b>Additional Information on Hawkeye Aircraft Available at:</b>
<b>Mike McCracken</b>	<a href="http://www.Hawkeye-Aircraft.com">www.Hawkeye-Aircraft.com</a>
<b>President</b>	Aircraft Subject to Prior Sale / Withdrawal from Market
O: 727.796.0903	Aircraft Specifications are Subject to Buyer's Verification
M: 813.240.0929	
<a href="mailto:Mike@Hawkeye-Aircraft.com">Mike@Hawkeye-Aircraft.com</a>	